

Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

# FLAMMABILITY TEST REPORT

<b>Report No.:</b> LEI18030003A <b>Supplementary to:</b> LEI18023994A	Date Received: 20/02/17 Date T	ested: 26/02/17	1 <sup>st</sup> Date Issued: 27/02/17 Supplementary Issued: 01/03/18
Company Name & Address:	ZIMMER + ROHDE GMBH ZIMMERSMÜHLENWEG 14 - 18 61440 OBERURSEL / FRANKFURT		
Contact Name:	JULIA SCHMIRALI		
Sample Details			
Order No.:	Not stated		
Description:	Faux Leather		
Ref/Style No.:	10764 Havanna		
Colour:	Cream		
Quality:	Not stated		
Supplier:	Not stated		
Batch No.:	Not stated		
Intended Use:	Upholstery		
Quoted Fibre Composition:	75% PVC, 25% Polyester		
Retailer:	Not stated		
Sample Description:	Cream coloured faux leather with	n white coloured bac	king

Test Method	Pre Treatment	Requirement	Result	
BS 5852: Part 1: 1979, Ignition source 0 (Cigarette)	Water soaked as clause 4.2 to 4.5 of BS 5651:1978 as modified by The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended) then line dried.	Compliance with Schedule 4 Part 1 (The cigarette test) of The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended).	Complies	
<b>Note:</b> Fabric was submitted for test rather than the upholstery composite so as suggested by The Guide to the Furniture Regulations the cover fabric was tested for cigarette resistance using standard polyurethane foam (non-modified) as this will give the furniture manufacturer a good indication of its likelihood to pass the cigarette test for the finished article				
BS 5852: Part 1: 1979, Ignition source 1 (Match)	Water soaked as clause 4.2 to 4.5 of BS 5651:1978 as modified by The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended) then line dried.	Compliance with Schedule 5 Part 1 (The match test) of The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended).		

STEVEN OWEN (Technical & Operational Excellence Manager)

Allallet

ANDREW HALLETT (Flammability Team Leader) CAROLE SPOWART (Flammability Administrator)

Report No.: LEI18030003A Supplementary to: LEI18023994A Page 1 of 2

ITS Testing Services (UK) Ltd Registered in England No. 1408264. Registered Office: Academy Place, 1-9 Brook Street, Brentwood, Essex, CM14 5NQ









Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

## FLAMMABILITY TEST REPORT

Test Specification	
Test Method:	BS 5852: Part 1: 1979 as modified by Schedule 4 Part 1 & Schedule 5 Part 1 of
	The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended).
Ignition Source:	Ignition source 0: Filterless cigarette
	Ignition source 1: Butane Gas flowing at 45ml/min @ 25°C.
Flame Application Time:	20±1 seconds
Side Tested:	Face

### **Filling Specification**

Filling Type: Supplier / Grade: Size: Density / Hardness: Polyurethane foam Carpenter / RP21130 unmodified 450 X 300 X 75mm (back) & 450 X 150 X 75mm (seat) 20-22 kg/m<sup>3</sup> / Type B, 130N

#### Pre-treatment / Durability procedure

Water soaked as clause 4.2 to 4.5 of BS 5651:1978 as modified by The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended) then line dried.

#### **Conditioning**

Prior to Testing:At least 72 hours in ambient indoor conditions, then at least 16 hours in an<br/>atmosphere having a temperature of 20±5°C and a relative humidity of 50±20%<br/>Temperature between 15°C & 30°C. Relative humidity between 20% & 70%

#### Test Results

"The following test results relate only to the ignitability of the combinations of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use."

Ignition source 0 (Test 1):	The cigarette failed to burn its complete length, there was no flaming or progressive smouldering. ( <b>Pass</b> )
Ignition source 0 (Test 2):	The cigarette failed to burn its complete length, there was no flaming or progressive smouldering. ( <b>Pass</b> )
Ignition source 1 (Test 1):	Flaming ceased with the removal of the burner, there was no progressive smouldering. ( <b>Pass</b> )
Ignition source 1 (Test 2):	Flaming ceased with the removal of the burner, there was no progressive smouldering. ( <b>Pass</b> )

#### **Conclusions**

The composite tested meets the requirements of Schedule 4 Part 1 (The cigarette test) of The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended). <u>PASS.</u>

The fabric tested meets the requirements of Schedule 5 Part 1 (The match test) of The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended). **PASS.** 

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have <u>aimed</u> to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Report No.: LEI18030003A Supplementary to: LEI18023994A Page 2 of 2





