

Zimmer + Rohde GmbH
 Frau Theresa Wilke
 Zimmersmühlenweg 14-18
 61440 Oberursel

Textilforschungsinstitut
 Thüringen-Vogtland e. V.
 Akkreditierte Prüfstelle

Zeulenrodaer Str. 42
 07973 Greiz - Germany

Test report No. 388/2/19

Page 1 of 2

Klob

14.08.2019

Customer:	Ms Theresa Wilke
Assignment from:	05.08.2019
Received:	07.08.2019
Samples:	<u>5 pieces of fabric</u> - article 10-A1045 - article 10-A1345 - article 10-A1346 - article 10-A1347 - article 10-A1397
Test:	Light transmission
Sampling:	By customer
Test procedure:	According to DIN EN 410
Date of analysis:	13.08.2019
Test results:	Page 2 and measurement reports

Durch die DAkkS
 Deutsche Akkreditierungsstelle GmbH
 akkreditiertes Prüflaboratorium

In der Anlage zur Akkreditierungsurkunde sind alle akkreditierten Prüfverfahren aufgeführt. Auf Wunsch wird die Urkunde zugestellt.



Test results:

Sample	Light transmission
	[%]
10-A1045	0,0
10-A1345	0,2
10-A1346	0,1
10-A1347	0,2
10-A1397	0,1

You can find the single values of the light transmission in the measurement reports.

The testing results are exclusively related to this sample under conditions are received.
Without written permission of the testing laboratory it is inhibited to copy this report partially.



Dr. U. Klobes
Head of the testing centre