

TITV e. V. • Zeulenrodaer Str. 42 • 07973 Greiz

ZIMMER + ROHDE GmbH
Zimmersmühlenweg 14-18
61440 Oberursel / Taunus**Test report 281/23**

Klob

24/08/2023

page 1 of 2

Customer: Ms. Oda Nimmer
Assignment from: 03/08/2023
Received: 14/08/2023Assignment:

No.	Test	Standard
		Test conditions
1.	Light transmission	DIN EN 410
		-

Samples:

Coding for test	Identification by customer
Sample 1	<u>Woven fabric</u> Article 10976 Material composition: 56 % PES FR RE / 44 % PES FR

Sampling: The samples were taken by the customer.Realisation
of the test:

The measurement samples were taken und tested in compliance with the above-mentioned regulations.

Testing period: 22/08/2023 – 24/08/2023

Test results:1. Light transmission

Sample 1	Light transmission [%]
Article: 10976	0.0

You can find the single values of the light transmission in the measurement report.

The testing results are exclusively related to the sample under conditions as received.

Without written permission of the testing laboratory it is inhibited to copy this report partially.



Dr Klobes
Head of the Testing Centre



Enclosure: measurement report of light transmission

Licht-Transmissionsgrad nach DIN EN 410

Gemessen am UV-2450PC mit interner Ulbrichtkugel

Prüfnummer: 281/23
Muster: Art. 10976

Datum: 24. August 2023
Bearbeiter: Gruner



	Transmissionsgrad / %		
Messung 1	0,0		Mittelwert
Messung 2	0,0		STABW
Messung 3	0,0		
Der Transmissionsgrad der Probe:		-0,0001 bzw.	-0,01 %

Gruner